

Issued Date: 06/21/2017

Andrew Dowd The Whiting-Turner Contracting Co. 4222 E Thomas Rd. Suite 320 Phoenix, AZ 85018

DETERMINATION OF NO HAZARD TO AIR NAVIGATION FOR TEMPORARY STRUCTURE

The Federal Aviation Administration has conducted an aeronautical study under the provisions of 49 U.S.C., Section 44718 and if applicable Title 14 of the Code of Federal Regulations, part 77, concerning:

Structure: Construction Equipment Tower Crane Block 23

Location: Phoenix, AZ

Latitude: 33-26-53.31N NAD 83

Longitude: 112-04-16.90W

Heights: 1087 feet site elevation (SE)

400 feet above ground level (AGL) 1487 feet above mean sea level (AMSL)

This aeronautical study revealed that the temporary structure does exceed obstruction standards but would not be a hazard to air navigation provided the condition(s), if any, in this letter is (are) met:

SEE ATTACHMENT FOR ADDITIONAL CONDITION(S) OR INFORMATION

This determination is based, in part, on the foregoing description which includes specific coordinates and heights. Any changes in coordinates and/or heights will void this determination. Any future construction or alteration, including increase to heights, requires separate notice to the FAA.

This determination does include temporary construction equipment such as cranes, derricks, etc., which may be used during actual construction of a structure. However, this equipment shall not exceed the overall heights as indicated above. Equipment which has a height greater than the studied structure requires separate notice to the FAA.

This determination concerns the effect of this temporary structure on the safe and efficient use of navigable airspace by aircraft and does not relieve the sponsor of compliance responsibilities relating to any law, ordinance, or regulation of any Federal, State, or local government body.

A copy of this determination will be forwarded to the Federal Aviation Administration Flight Procedures Office if the structure is subject to the issuance of a Notice To Airman (NOTAM).

If you have any questions, please contact our office at (425) 227-2625, or paul.holmquist@faa.gov. On any future correspondence concerning this matter, please refer to Aeronautical Study Number 2017-AWP-3953-OE

Signature Control No: 329288472-335922967 (TMP)

Paul Holmquist Specialist

Additional Condition(s) or Information for ASN 2017-AWP-3953-OE

Proposal: To construct and/or operate a(n) Construction Equipment to a height of 400 feet above ground level, 1487 feet above mean sea level.

Location: The structure will be located 3.11 nautical miles west of PHX Airport reference point.

Part 77 Obstruction Standard(s) Exceeded and Aeronautical Impacts, if any:

Section 77.17 (a) (2) by 141 feet - a height that exceeds 1346 feet above mean sea level within 3.11 nautical miles of PHX.

Section 77.17 (a) (5) a height that affects an Airport Surface by penetrating:

Section 77.19 (b) Conical Surface by 65 feet as applied to PHX.

Section 77.19 (e) Transitional Surface by 76 feet as applied to PHX.

This structure would exceed the PHX VFR traffic pattern airspace in the Part 77 77.17(a)(2) Surface by three (3)) feet as defined in FAA JO 7400.2K, 6-3-8, Evaluating Effect on VFR Operations.

Preliminary FAA study indicates that the above mentioned structure would:

have no effect on any existing or proposed arrival, departure, or en route instrument flight rules (IFR) operations or procedures.

have no physical or electromagnetic effect on the operation of air navigation and communications facilities. have no effect on any airspace and routes used by the military.

Based on this aeronautical study, the structure would not constitute a substantial adverse effect on aeronautical operations or procedures because it will be temporary. The temporary structure would not be considered a hazard to air navigation provided all of the conditions specified in this determination are strictly met.

As a condition to this Determination, the structure is to be marked/lighted in accordance with FAA Advisory circular 70/7460-1 L Change 1, Obstruction Marking and Lighting, flags/red lights - Chapters 3(Marked),4,5(Red),&12.

Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately to (877) 487-6867 so a Notice to Airmen (NOTAM) can be issued. As soon as the normal operation is restored, notify the same number.

It is required that the manager of the Phoenix Sky Harbor International Airport construction coordination office, at (602) 768-3996, be notified at least 3 business days prior to the temporary structure being erected and again when the structure is removed from the site.

It is required that the manager of Phoenix Sky Harbor Airport Traffic Control Tower, at 602-306-2569 or (602) 306-2520 be notified at least 3 business days prior to the temporary structure being erected and again when the structure is removed from the site. Additionally, please provide contact information for the onsite operator in the event that Air Traffic Control requires the temporary structure to be lowered immediately.

This determination expires on 12/21/2018 unless extended, revised, or terminated by the issuing office.

NOTE: REQUEST FOR EXTENSION OF THE EFFECTIVE PERIOD OF THIS DETERMINATION MUST BE E-FILED AT LEAST 15 DAYS PRIOR TO THE EXPIRATION DATE. AFTER RE-EVALUATION OF CURRENT OPERATIONS IN THE AREA OF THE STRUCTURE TO DETERMINE THAT NO SIGNIFICANT AERONAUTICAL CHANGES HAVE OCCURRED, YOUR DETERMINATION MAY BE ELIGIBLE FOR ONE EXTENSION OF THE EFFECTIVE PERIOD.

TOPO Map for ASN 2017-AWP-3953-OE



